Search Notes

Application/Control No.	Applicant(s)/Patent under Reexamination	
	Reexamination	

09/993,752 Examiner DAVENPORT ET AL.
Art Unit

Robert N. Kang

2622

RNK

SEARCHED				
Class	Subclass	Date	Examiner	
358	1.15	12/6/2005	RNK	
358	1.16	12/6/2005	RNK	
358	444	12/6/2005	RNK	
347	15	12/20/2005	RNK	
347	225	12/20/2005	RNK	
364	518	12/20/2005	RNK	
395	115	12/20/2005	RNK	

INTERFERENCE SEARCHED				
Class	Subclass	Date	Examiner	
-	·			
Davenpor	t/IBM Corp	12/20/2005	RNK	

SEARCH NOT (INCLUDING SEARCH		
	DATE	EXMR
("beam detect" or BD) same "print engine"	12/6/2005	RNK
asic same (increase near bandwidth)	12/6/2005	RNK
print\$3 same asic same (bd or "beam detect")	12/6/2005	RNK
(shorten or reduce or decrease or compress) near (BD or "beam detect" or beam\$1 detect"	12/6/2005	RNK
(BD or "beam detect" or beam\$1detect) near3 delay	12/6/2005	RNK
Edward Coles, SPE	12/21/2005	RNK
Twyler Lamb, PE	12/6/2005	RNK
Mark Wallerson, PE	12/21/2005	RNK